


**JIMDOA®**

**Nail Drill**


**User Manual**



JIMDOA makes you more attractive

**JMD-109P**

**NAIL DRILL SYSTEM**



**NAIL DRILL SYSTEM**

**SPECIFICATION**

- 1.Input Voltage:DC: 5V == 2A
- 2.Output Voltage:DC: 2-5V
- 3.Power:15W
- 4.Weight:1kg
- 5.Dimension:L29.4\*W8.17\*H6.1 (cm)


**PRECAUTION**

- 1.Do NOT disassemble the handpiece
- 2.Do NOT drop the handpiece
- 3.Do not work in a humid environment.
- 4.Operating Environment Humidity:30-75%
- 5.Operating Environment Temperature:+10°C-26°C
- 6.Turn off the power when changing the bits
- 7.Make sure the power switch is off before plugging in the power cord to avoid an unexpected injury due to sudden start.


-1 -

**SET AND OPERATION**


**1.Set drill bits**




Turn left side clockwise until you hear it click into the place



Take out the original bit



Insert the 3/32 " size bit



Turn right side anti-clockwise to lock the bit tightly

**2. Operation Steps:**

- 1.When you touch the on-off key " (power icon) " for 2 seconds, the "Jimdoa" logo will show up for 2 seconds on the screen, then can see the speed "00" of the handpiece, battery level display on the screen, and the machine enters the standby state.
2. When touch again the on-off key " (power icon) ", the nail drill switch to R from F, R stands for reverse rotation and F stands for forward rotation.
3. When you touch " ^ SPEED " key, it is the up shift key 0-35(RPM\*1000) , long press can continuously jump to 35(RPM\*1000), or adjust to the desired setting gear, please pay attention, when the speed jump to 35(RPM\*1000), touch again " ^ SPEED " key, The display 35 gear is flashing, which means that it is ready to enter gear 35 to 0,the speed start from 35-0-35(RPM\*1000) again.
4. Do not use the machine for a long time, please connect the charge base with 5V 2A USB charger, when you put the handpiece into charge base, it is automatic charging until the battery capacity up to 99% that means full charge.

-3 -

**说明书工艺说明**

**1.250G铜板纸印刷覆亚膜。**

**2.说明书尺寸242\*200mm.**